




OFFICE OF THE MARION COUNTY SURVEYOR  
 SECTION RECORD CORNER  
 SECTION 16 TOWNSHIP 15 RANGE 2  
 DATE: 4-23-01 4-18-06  
 PARTY CHIEF: Wilcoxen - Kiste  
 CREW: \_\_\_\_\_  
 TYPE OF MARKER: PK not found Harrison  
 METHOD OF ESTABLISHMENT: County: 5-17-96

IN. S.P.C. E ZONE, NAD 83  
 NAME: 15021605  
 N: 499066.5102(m)  
 E: 44247.0087(m)

This is a Record Corner set  
 by Park Engineering:



15021605

REF.	DISTANCE	DESCRIPTION
1.	110' +/-	Due S to C/L of New Church Road
2.	109.00'	SE corner of stone column 1st stone up
3.	33.85'	Mag nail w/brass washer SE PwP#142-551 8"up
4.	43.90'	Mag nail w/brass washer NE PwP#143-551 8"up

A survey by D.B. Hasbrook on May 6, 1853 indicates no stone but the following witnesses: 16" oak bearing south 72.50 degrees, thence east 31 links; and a 24" sycamore bearing north 82.25 degrees, thence east 18 links. (Wayne Legal Book p. 31) A survey by Wm. P. Smith on May 18, 1869 indicates no stone but the same witnesses as previous survey in 1853. (Wayne Legal Book p. 60) Corner referenced by Park engineering on 10/1/81 and called a R.R. spike. Corner referenced by Wilcoxen on 10/2/89 and called a R.R. spike with a cut X. Corner referenced by Wilcoxen on 5/17/96 and called a p.k. Nail. Corner referenced by Wilcoxen on 4/23/01 and called a p.k. Nail. Corner excavated by Wilcoxen on 10/9/01 and a R.R. spike was found 6" down. No other points were found. A #205 cast iron Harrison monument was set in position as the corner.